United States Department of the Interior Heritage Conservation and Recreation Service

National Register of Historic Places Inventory—Nomination Form

See Instructions in How to Complete National Register Forms
Type all entries—complete applicable sections

e meres	
For HCRS use o	nly
received	
date entered	
115666	

1. Nam	complete applicable	e sections				
· · · · ·	Α					
historic	St. Vincent de Paul Catholic Church					
and/or common	Old St. Vincent's Catholic Church					
2. Loca	ation					
street & number	131 South Main S	treet		not for publication		
city, town	Cape Girardeau	vicinity of	congressional district	#10-Hon. Bill Burliso		
state	Missouri co	ode 029 county	Cape Girardeau	code 031		
3. Clas	sification					
Category district building(s) structure site object	Ownership public _X private both Public Acquisition in process being considered	Status _X_ occupied unoccupied _X_ work in progress Accessiblex_ yes: restricted yes: unrestricted no	Present Use agriculture commercial educationalX_ entertainment government industrial military	museum park private residence X religious scientific transportation other:		
4. Own	er of Prope	erty				
name	ddedooridaeonidk	iwork/conedaethchocane	xxx (see continua	tion sheet)		
street & number	ADBARK XBARCK XBARBOK	ex				
city, town	agangki xxas	vicinity of	state	XBCXfxCx xix xuxoccxiXX		
5. Loca	ation of Leg	gal Descripti	on			
courthouse, regi	stry of deeds, etc.	ecorder's Office, Ca	pe Girardeau County	/ Courthouse		
•		ourthouse Square		•		
city, town	J	ackson	\ state	Missouri 63755		
6. Rep	resentation	n in Existing	Surveys			
title Missouri	Historic Sites Ca	talogue has this pi	operty been determined e	elegible? yes _x no		
date 1963	miscoric srces ca	ca rogue p.				
	Importance and the second			ate county local		
		<u>Historical Society o</u>		Niconai CEOO		
city, town	Columbia,		state	Missouri 65201		

NPS Form 10-900-a (7-81)

United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form

ST. VINCENT DE PAUL CATHOLIC CHURCH

Continuation sheet

Item number

OMB NO. 1024-0018 EXP. 12/31/84

For NPS use only
received
date entered

Page

1. Bernard F. Law, Bishop of Springfield-Cape Girardeau, a Corporation Sole Diocese of Springfield-Cape Girardeau 200 McDaniel Building Springfield, Missouri 65806

United States Department of the Interior Heritage Conservation and Recreation Service

National Register of Historic Places Inventory—Nomination Form ST. VINCENT DE PAUL CATHOLIC CHURCH

For HCRS use only received date entered

Continuation sheet

Item number

6

Page

Missouri State Historical Survey 1979, 1980 state Historic Preservation Program, P.O. Box 176 Jefferson City, Missouri 65101

7. Description

Condition excellent deteriorated good ruins fair unexposed	Check one unaltered _X_ altered	Check one _X_ original site moved date	
---	---------------------------------	--	--

Describe the present and original (if known) physical appearance

The Church of St. Vincent de Paul, now known as Old St. Vincent's Church, is located in a residential neighborhood of Cape Girardeau, Missouri, two blocks south of the town's central business district. It is surrounded by buildings dating primarily to the period between 1850 and 1920.

The church, which measures approximately 129' from east to west and 67' from north to south, features a design scheme of three by seven bays and is constructed of red brick with sandstone trim, painted cream, on a foundation of sandstone. The building is capped by a gabled roof covered with asphalt shingles and is designed in the Gothic Revival style with several elements drawn from the English Perpendicular These include, on the exterior, the vertically oriented perpendicular wooden mullions, the tall and slim window and vent openings, the flat walled western apse and the tower which was designed for the building but never built (photo #8). The present ogival dome which rests on the tower in the central bay of the primary facade is at least the third design scheme which has been proposed for this feature. The church was originally constructed without a central tower (photo #9). After 1880 but prior to 1905 a vestibule was added to the primary facade and a pyramidal steeple was constructed over the central bay (photo #10). ²This steeple was struck by lightning twice and finally destroyed in 1912. The base of the 1905 tower remained and the present cupola was constructed above in 1912. The exterior brick walls of the church were stuccoed in 1923 as part of a conservation effort. This stucco coating was removed by sandblasting in the remodeling of 1951-1953 and the resulting pockmarked surface was unskillfully repointed and treated with waterproofing containing red pigment. The present carved oak doors were added to the main entrance in 1926. to a traffic entaining ofthe

The interior to the church features clustered piers of unknown material, possibly wood, coated with plaster which support a hammer beam wooden ceiling. This ceiling exhibits plainly molded hammer beams and braces supporting open work trefoil medallions flanking Tudor arched collar braces. Above, a pediment with a central open work quatrefoil supports a gabled roof. To the west in the flat backed apse, a triple lancet window was covered inside and out at an unknown date with enamel paint to act as a backdrop for the large wooden crucifix which hangs there today. The color scheme of the interior features beige walls, rose beige trim and red carpeting.

All the windows and niches in the sanctuary and aisles are crowned with head molds which terminate in anthropomorphic label stops. The walls, column surfaces and all of the decorative effects within the church are executed in plaster. In the restoration of 1951-1953 all the plaster was removed from the interior and all details were removed, recast and replaced and the walls were replastered. At the same time all the glass in the windows was replaced, though the original wooden mullions were retained. In addition, the heating system was refurnished, modern wiring and lighting were installed and soundproofed confessionals were constructed at the east end of the building.

United States Department of the Interior Heritage Conservation and Recreation Service

National Register of Historic Places Inventory—Nomination Form

ST. VINCENT DE PAUL CATHOLIC CHURCH

Continuation sheet

Item number 7

For HCRS use only received date entered

Page 1

At the southwest and northwest extremes of the building other alterations are evident. Exterior arched doorways, which have been sealed with brick, originally opened onto very narrow spiral stairways leading to small second floor rooms over the sacristies. Only the stair to the south remains. These small rooms have grilled windows which overlook the main alter. It is believed that these spaces served as seating areas either for nuns of the nearby St. Vincent's Academy or for slaves of the original parishioners.

An examination of the exterior of this building reveals that all brick, sand-stone and mortar is in an extremely friable condition and is deteriorating rapidly. Evidently, the waterproof coating given to the exterior in the 1950's has not been effective for many years. In addition, all wooden trim on doors and windows is peeling and needs repainting. Inside, watermarks on the ceiling indicate water damage in several areas, but a new roof is currently being installed.

Footnotes

- 1. Louis Houck, "City School System Gets Start in Church Basement", Southeast Missourian; May 7, 1969.
- 2. These features are not seen in the view of the church dated to 1880 but are seen in a 1905 view.
- 33 Information on alterations is taken from the draft National Register Inventory-Nomination Form by Miss Laura St. Ann Keller and from A History of St. Vincent's Church, Centennial Booklet, 1853-1953 (Cape Girardeau: St. Vincent's Church, 1953) and "Out of the Past", Southeast Missourian, December 2, 1950.

8. Significance

Period prehistoric 1400–1499 1500–1599 1600–1699 1700–1799 X 1800–1899 1900–	Areas of Significance—C — archeology-prehistoric — archeology-historic — agriculture _X architecture — art — commerce — communications	community plan conservation economics education engineering	-	science sculpture social/ humanitarian theater
Specific dates	1853	Builder/Architect	John Lansman - Builder Thomas Waryng Walsh - Ar	chitect

Statement of Significance (in one paragraph)

St. Vincent de Paul Catholic Church, now Old St. Vincent's Church, in Cape Girardeau, Missouri is significant as the unique local example of English Perpendicular Gothic Revival architecture. It was designed by the noted Missouri architect, Thomas Waryng Walsh, and has served as a center of religious activity in Cape Girardeau for over a century.

Thomas Waryng Walsh was born in Kilkenny, Ireland in 1827. He was educated at Trinity College in Dublin and he followed his father's profession of architect after apprenticing under Sir William Dean Butler. Walsh arrived in St. Louis in 1849 and soon secured many fine commissions which established him as an architect of note. These included the Second Empire Four Courts Building and the English Gothic Revival St. Francies Xavier Church and St. Louis University Campus Buildings, all in St. Louis, Missouri.²

The story of the Catholic faith in Cape Girardeau began in 1821 when priests began to make periodic visits to settlers in the area. By 1833 the church had secured the land where Old St. Vincent's stands today and by 1836 the town had its first resident priest, Reverand John Odin. By April, 1838, the cornerstone for the church building was laid on the site by Bishop Rosati of St. Louis. Though this first church was of substantial stone construction, it was destroyed by a tornado in 1850. The present church was constructed over the foundations of the old in 1853.

Morship at this church has continued uninterrupted from 1853 to the present. On December 1, 1977 the status of this church was changed from a parish church to that of a chapel of ease of the Parish of St. Mary's Cathedral due to the construction of a new Church of St. Vincent de Paul and the organization of its new parish. In addition, the name of the building was changed to Old St. Vincent's Church at this time to distinguish it from the new church. With this change the administration of the old building was passed to the Pastor of St. Mary's Cathedral Parish with legal title retained by the Vincentian Fathers. By a joint decision of the Bishop of the Springfield-Cape Girardeau Diocese and the Superior of the Vincentian Fathers the cost of ordinary maintenance of the building is borne by those members of Sair Mary's Cathedral Parish who chose to make Old St. Vincent's their regular place of worship. The people are also responsible for generating funds for the renovation and the preservation of the building since no funds from the parish, the Vincentain Fathers or the Diocese are provided.

At present the building serves as a place of religious services on Sunday mornings, and it is occasionally the location of other religiously oriented community events such as choral concerts presented by the local Southeast Missouri State University Department of Music.⁴

United States Department of the Interior Heritage Conservation and Recreation Service

National Register of Historic Places Inventory—Nomination Form

ST. VINCENT DE PAUL CATHOLIC CHURCH

Continuation sheet Item

Item number

received date entered

For HCRS use only

Page 1

Footnotes

- 1. Thomas Waryng Walsh has been designated as architect based on a statement by Louis Houck in "City School System Gets Started in Church Basement", Southeast Missourian, May 7, 1969 and on stylistic grounds through comparison Walsh's known designs.
- 2. John Albury Bryan, Missouri's Contribution to American Architecture, (St. Louis: St. Louis Chapter-American Institute of Architects, 1928), p. 51 and William Hyde and Howard Conard, Encyclopedia of the History of St. Louis (New York: Southern Historical Co., 1899), pp. 2399-2400. For illustrations of Walsh's buildings see George McCue, The Building Art in St. Louis (St. Louis: St. Louis Chapter-American Institute of Architects, 1967), p. 49 and Bryan, pp. 57, 79.
- 3. A History of St. Vincent's Church, Centennial Booklet, 1853-1953 (Cape Girardeau: St. Vincent's Church, 1953), p. 3.
- 4. "Old St. Vincent's Setting for Handel's 'Te Deum'", Southeast Missourian, April 9, 1978.

9. Major	Bibliogra	phical	Referer	ices			-
Cape Gir 2. Bryan, Jo St. Loui	y of St. Vincenardeau: St. Vincenson Albury.`Miss: St. Louis C	ncent's Chur scouri's Cor hapter-Ameri	ch, 1953. htribution to	o American A	rchitecture.	· · · · · · · · · · · · · · · · · · ·	_
10. Geog	<u>graphical</u>	Data					_
Acreage of nominate Quadrangle name UMT References	d property <u>1.20</u> Cape Girardeau,	MO-ILL		Quadra	ingle scale <u>1:2</u>	24,000	_
A 1,5 2 7,6 Zone Easting C	6 ₁ 8 ₁ 0 4 ₁ 13 ₁ 1 Northing		B Zone D	Easting	Northing Line	111 ·	
in the City of west corner of	lescription and jus Cape Girardeau ; lot 18 Range "A West line of t	more particu "-and run th	llarly descr mence east a	ibed as follo long the Nort	ows: Commend th line of Wi	e at the S lliams Str	outh- eet
List all states and	counties for prope	erties overlap	oing state or c	ounty boundari	es		
state	<u> </u>	code	county	. • ,	code		
state		code	county		code		
11. Form	Prepare	d By		- †			_
name/title 1.	Noelle Soren, Department of	Natural Res	ources				- -
	Historic Pres			ate October 2			_
street & number	P.O. Box 176	711. A	/ 28 ម្ខាន់កំនួន t ឲ	elephone de 314	:751 4096		- '
city or town	Jefferson Cit				ri 65102	·. · ·	-
12. State	Historic	Preser	vation	Officer	Certific	ation	-
The evaluated signific	cance of this propert	y within the stat	e is:	·			
na	ationals	tateX	local				_
665), I hereby nomina according to the crite	ate:Historic:Préserva ate this property for li ria and procedures s vation Officer signatu	nclusion in the Net forth by the H	lational Register	and certify that i	it has been evalua		
	oric Preservati		•		22-Feb	87	-
For HCRS use only	Department of No			•			
Keeper of the Natio			i prikan	date			
Chief of Registratio	n .	· · · · · · · · · · · · · · · · · · ·		· · · · · · · · · · · · · · · · · · ·	1 10 10]

United States Department of the Interior Heritage Conservation and Recreation Service

National Register of Historic Places Inventory—Nomination Form

ST. VINCENT DE PAUL CATHOLIC CHURCH

received date entered

Continuation sheet

Item number

Page


1

- Houck, Louis. "City School System Gets Start in Church Basement". Southeast Missourian, May 7, 1969.
- Hyde, William and Conard, Howard. Encyclopedia of the History of St. Louis. New York: Southern Historical Co., 1899.
- 5. "Old St. Vincent's Setting for Handel's "Te Deum'", Southeast Missourian, April 9, 1978.
- 6. McCue, George. The Building Art in St. Louis. St. Louis: St. Louis Chapter-American Institute of Architects, 1969.


Item Number 11

Page 1


- 2. Miss Laura St. Ann Keller Old St. Vincent's Catholic Church Westlane, East Rodney Drive 314:334-5784 Cape Girardeau, Missouri 63701
- James Denny, Chief Nominations and Survey Department of Natural Resources Historic Preservation Program P.O. Box 176 314:751-4096 Jefferson City, Missouri 65102




SAINT VINCENT'S CATHOLIC CHURCH IRUNCENT, MISSOURI



FLOOR PLAN SAINT VINCENT'S CATHOLIC CHURCH IRUCENT'S CATHOLIC CHURCH






(HTRON NAJG ROOJ3

SAINT VINCENT'S CATHOLIC CHURCH-CAPE GIRARDEAU, MISSOURI

Prepared by Whitworth Foust and Steames, Inc., Cape Girardeau, Missouri



MAJG BTIE

SAINT VINCENT'S CATHOLIC CHURCH-CAPE GIRARDEAU, MISSOURI

Prepared by Whitworth Foust and Stearnes, Inc., Cape Girardeau, Missouri

ST. VINCENT DE PAUL CATHOLIC CHURCH #1 of 10 131 S. Main, Cape Girardeau, Cape Girardeau County. MO.

Photographer: Gordon McBride


June, 1979

Neg. Loc.: 625 Belleview, Cape Girardeau, MO.


63701

Primary (east) facade.

NR2C



ST. VINCENT DE PAUL CATHOLIC CHURCH #2 of 10 131 S. Main, Cape Girardeau, Cape Girardeau County, MO.
Photographer: Jim Denny
September, 1980
Department of Natural Resources, P.O. Box 176, Jefferson City, MO. 65101
Primary (east) facade, detail, main entryway.
Note the especially deteriorated condition of the brick



ST. VINCENT DE PAUL CATHOLIC CHURCH #3 of 10
131 S. Main, Cape Girardeau, Cape Girardeau
County, MO.
Photographer: Jim Denny
September, 1980
Department of Natural Resources, P.O. Box 176,
Jefferson City, MO. 65101
South side.



ST. VINCENT DE PAUL CATHOLIC CHURCH #4 of 10 131 S. Main, Cape Girardeau, Cape Girardeau County, MO.


Photographer: Jim Denny

September, 1980

Department of Natural Resources, P.O. Box 176,

Jefferson City, MO. 65101 View to northeast of southwest corner. Note entryway which has been closed in the small

tower in the corner.



ST. VINCENT DE PAUL CATHOLIC CHURCH #5 of 10 131 S. Main, Cape Girardeau, Cape Girardeau County, MO.
Photographer: Jim Denny
September, 1980
Department of Natural Resources, P.O. Box 176, Jefferson City, MO. 65101
View to southeast of northwest corner and west side.



ST. VINCENT DE PAUL CATHOLIC CHURCH #6 of 10 131 S. Main, Cape Girardeau, Cape Girardeau County, MO.

Photographer: Gordon McBride June, 1979

Neg. Loc.: 625 Belleview, Cape Girardeau, MO.

63701

Interior, view to east.



ST. VINCENT DE PAUL CATHOLIC CHURCH #7 of 10 131 S. Main, Cape Girardeau, Cape Girardeau County, MO.
Photographer: Jim Denny September, 1980

Department of Natural Resources, P.O. Box 176, Jefferson City, MO. 65101
Interior, view to west.



ST. VINCENT DE PAUL CATHOLIC CHURCH #8 of 10 131 S. Main, Cape Girardeau, Cape Girardeau County, MO.
Photographer: Lueders Studio

"Capital View of Cape Girardeau", engraving by A. Bottger showing in two views the intent of the architect in the design of the steeple. Date ca. 1860.



ST. VINCENT DE PAUL CATHOLIC CHURCH #9 of 10 131 S. Main, Cape Girardeau, Cape Girardeau County, MO.


Photographer: Unknown

Prior to 1905

Neg. Loc.: H. Riley Bock, New Madrid, MO.

63869


Primary (east) facade as originally constructed without tower and vestibule.



ST. VINCENT DE PAUL CATHOLIC CHURCH #10 of 10 131 S. Main, Cape Girardeau, Cape Girardeau County, MO.


Photographer: Southeast Missouri Drummers
Magazine
1905


Neg. Loc.: Gordon McBride, 625 Belleview, Cape Girardeau, MO. 63701
Primary (east) facade with steeple which was destroyed in 1912.



EXTRA




















KODAK SAFETY FILM 5062 KODAK SAFETY FILM 5062 AK SAFETY FILM 5062







→16A

